ENVIRONMENTAL CHEMISTS

Analysis For Total Metals By EPA Method 200.8

 Client ID:
 M07285

 Date Received:
 06/17/11

 Date Extracted:
 06/22/11

 Date Analyzed:
 06/22/11

 Matrix:
 Water

 Units:
 ug/L (ppb)

Client: Alaskan Copper Works
Project: Metro Self Monitor, F&BI 106257

Lab ID: 106257-01 x10 Data File: 106257-01 x10.014

Instrument: ICPMS1 Operator: AP

Lower Upper Internal Standard: % Recovery: Limit: Limit: Germanium 92 60 125

Concentration
ug/L (ppb)

Chromium 311
Nickel 282
Copper 157
Zinc <10

ENVIRONMENTAL CHEMISTS

Analysis For Total Metals By EPA Method 200.8

Client ID: Method Blank
Date Received: Not Applicable
Date Extracted: 06/22/11
Date Analyzed: 06/22/11
Matrix: Water
Units: ug/L (ppb)

Client: Alaskan Copper Works
Project: Metro Self Monitor, F&BI 106257
Lab ID: I1-420 mb

Data File: I1-420 mb.008 Instrument: ICPMS1 Operator: AP

Lower Upper Internal Standard: % Recovery: Limit: Limit: Germanium 93 60 125

Concentration ug/L (ppb)

Chromium <1
Nickel <1
Copper <1
Zinc <1

ENVIRONMENTAL CHEMISTS

Date of Report: 06/23/11 Date Received: 06/17/11

Project: Metro Self Monitor, F&BI 106257

QUALITY ASSURANCE RESULTS FOR THE ANALYSIS OF WATER SAMPLES FOR TOTAL METALS USING EPA METHOD 200.8

Laboratory Code: 106236-01 (Matrix Spike)

				Percent	Percent		
	Reporting	Spike	Sample	Recovery	Recovery	Acceptance	RPD
Analyte	Units	Level	Result	MS	MSD	Criteria	(Limit 20)
Chromium	ug/L (ppb)	20	2.66	102	107	67-132	5
Nickel	ug/L (ppb)	20	3.00	104	106	73-119	2
Copper	ug/L (ppb)	20	148	140 b	166 b	50-144	17 b
Zinc	ug/L (ppb)	50	261	107 b	112 b	46-148	5 b

Laboratory Code: Laboratory Control Sample

	Percent									
	Reporting	Spike	Recovery	Acceptance						
Analyte	Units	Level	LCS	Criteria						
Chromium	ug/L (ppb)	20	98	66-135						
Nickel	ug/L (ppb)	20	102	67-134						
Copper	ug/L (ppb)	20	104	66-134						
Zinc	ug/L (ppb)	50	103	57-135						

ENVIRONMENTAL CHEMISTS

Data Qualifiers & Definitions

- a The analyte was detected at a level less than five times the reporting limit. The RPD results may not provide reliable information on the variability of the analysis.
- A1 More than one compound of similar molecule structure was identified with equal probability.
- b The analyte was spiked at a level that was less than five times that present in the sample. Matrix spike recoveries may not be meaningful.
- ca The calibration results for this range fell outside of acceptance criteria. The value reported is an estimate.
- c The presence of the analyte indicated may be due to carryover from previous sample injections.
- d The sample was diluted. Detection limits may be raised due to dilution.
- ds The sample was diluted. Detection limits are raised due to dilution and surrogate recoveries may not be meaningful.
- dv Insufficient sample was available to achieve normal reporting limits and limits are raised accordingly.
- fb Analyte present in the blank and the sample.
- fc The compound is a common laboratory and field contaminant.
- hr The sample and duplicate were reextracted and reanalyzed. RPD results were still outside of control limits. The variability is attributed to sample inhomogeneity.
- ht Analysis performed outside the method or client-specified holding time requirement.
- ip Recovery fell outside of normal control limits. Compounds in the sample matrix interfered with the quantitation of the analyte.
- i The result is below normal reporting limits. The value reported is an estimate.
- J The internal standard associated with the analyte is out of control limits. The reported concentration is an estimate.
- ${
 m jl}$ The analyte result in the laboratory control sample is out of control limits. The reported concentration should be considered an estimate.
- jr The rpd result in laboratory control sample associated with the analyte is out of control limits. The reported concentration should be considered an estimate.
- js The surrogate associated with the analyte is out of control limits. The reported concentration should be considered an estimate.
- lc The presence of the compound indicated is likely due to laboratory contamination.
- L The reported concentration was generated from a library search.
- nm The analyte was not detected in one or more of the duplicate analyses. Therefore, calculation of the RPD is not applicable.
- pc The sample was received in a container not approved by the method. The value reported should be considered an estimate.
- pr The sample was received with incorrect preservation. The value reported should be considered an estimate.
- ve Estimated concentration calculated for an analyte response above the valid instrument calibration range. A dilution is required to obtain an accurate quantification of the analyte.
- vo The value reported fell outside the control limits established for this analyte.
- x The sample chromatographic pattern does not resemble the fuel standard used for quantitation.

and Danast To (787)	14000) 		SAMPLERS	si gnature)		=		>		-		Page #		of JD TIME												
Send Report To GERZUD THOMPSON Company ALASKAN CORPLE Works Address 628 S. Handel ST City State, ZIP SEATLE WA 98134			PROJECT NAME/NO. PO# MESTED SELF Monitor mo7285 REMARKS					Standard (2 Weeks) USH / du/ Rush charges authorized by SAMPLE DISPOSAL Dispose after 30 days																			
												hone #_Z~6-S71-603												□ Re	turn s	amples	tructions
																5150					ANA	TAS	SES REQ	UESTED	n Kin		
Sample ID	Lab ID	Date	Time	Sample Type	# of containers	TPH-Diesel	TPH-Gasoline	BTEX by 8021B	SVOCs by 8270	HFS	Cecurso				Notes												
28540M	01	9/16	11:00pm	HeO	1						1																
							\perp] 													
				_		J.		-																			
							1	Ŧ																			
					_						1 0																
Origin 1902 - 12 1902 at 1120																											
iedman & Bruya, Inc.		SIGNATU	RE		PRINT	NAI	Æ				COMP			DATE	TIME												
12 16th Avenue West	rolingustady:			JE10()(2) 3725 4205				Acu			6/	17/11	1:057														
attle, WA 98119-2029	Reinquished by:			VNH FBI				FBI		6	/17/11	1:05/M															

ENVIRONMENTAL CHEMISTS

James E. Bruya, Ph.D. Charlene Morrow, M.S. Yelena Aravkina, M.S. Bradley T. Benson, B.S. Kurt Johnson, B.S. 3012 16th Avenue West Seattle, WA 98119-2029 TEL: (206) 285-8282 FAX: (206) 283-5044 e-mail: fbi@isomedia.com

June 23, 2011

Gerald Thompson, Project Manager Alaskan Copper Works 628 South Hanford Seattle, WA 98134

Dear Mr. Thompson:

Included are the results from the testing of material submitted on June 17, 2011 from the Metro Self Monitor, F&BJ 106257 project. There are 4 pages included in this report. Any samples that may remain are currently scheduled for disposal in 30 days. If you would like us to return your samples or arrange for long term storage at our offices, please contact us as soon as possible.

We appreciate this opportunity to be of service to you and hope you will call if you have any questions.

Sincerely,

FRIEDMAN & BRUYA, INC.

Michael Erdahl Project Manager

Enclosures ACU0623R.DOC